

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

11/07/2023

Document Number:

403587228

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: <u>47120</u>	Contact Person: <u>Erik Mickelson</u>
Company Name: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Phone: <u>(720) 929-4306</u>
Address: <u>P O BOX 173779</u>	Fax: <u>()</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>	Email: <u>Erik_Mickelson@oxy.com</u>

Identification Information

API Number: 05 - <u> </u> - <u> </u>	OGCC Facility ID: <u>336650</u>	Initial Form 19 or 27 Document number: <u> </u>
Facility Name: <u>BELLA FEDERAL</u>	Facility Number: <u>36N-7HZ</u>	Facility Type: <u>LOCATION</u>
Location QtrQtr: <u>SESW</u>	Section: <u>8</u>	Township: <u>3N</u>
	County: <u>WELD</u>	Field Name: <u>WATTENBERG</u>
Range: <u>66W</u> Meridian: <u>6</u>		
Federal, Indian or State Lease Number: <u> </u>		

Information Submitted By:

Company Name: <u>Absaroka Solutions</u>	Agent Name: <u>Jordan Fleming</u>	Title: <u>Environmental Professional</u>
Phone Number: <u>7202448469</u>	Email: <u>jordan.fleming@absarokasolutions.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: <u>752520</u>	Facility Name: <u>7_3N_66W_Henrickson</u>	Facility Type: <u>Ground Water</u>
Location: QtrQtr: <u>SWSE</u>	Sec: <u>7</u>	Twp: <u>3N</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
County Name: <u>WELD</u>	Latitude: <u>40.234410</u>	Longitude: <u>-104.815514</u>

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: <u>114330</u>	Document Name: <u>Size of file in bytes: 28160</u>	File Name: <u>2023_07_18_7_3N_66W_Henrickson Isotech SIW COGCC.xls</u>
SampleType: <u> </u>	Matrix: <u> </u>	
Facility ID: <u>752520</u>	Sample ID: <u>653342</u>	Sample Name: <u>7_3N_66W_Henrickson</u>
		Sample Date: <u>07/18/2023</u>
Collection Point: <u>Stock</u>	Matrix: <u>WATER</u>	Pre Post: <u>Voluntary Post drill</u>
Project Number: <u> </u>	Remediation Number: <u> </u>	Complaint Number: <u> </u>
		NOAV Number: <u> </u>
Inspection Number: <u> </u>	Spill Number: <u> </u>	Laboratory: <u>ISOTECH</u>
		Lab Sample ID: <u>881912</u>

Batch ID: 114329 Document Name: Size of file in bytes: 36352 File Name: 2023_07_18_7_3N_66W_Henrickson Isotech NG4
ECMC.xls

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 653340 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/18/2023

Collection Point: Stock Matrix: GAS Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 881921

Batch ID: 114329 Document Name: Size of file in bytes: 36352 File Name: 2023_07_18_7_3N_66W_Henrickson Isotech NG4
ECMC.xls

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 653341 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/18/2023

Collection Point: Stock Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 881921

Batch ID: 114328 Document Name: Size of file in bytes: 31232 File Name: 2023_07_18_7_3N_66W_Henrickson Trip Blank
SGS ECMC.xls

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 653339 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/18/2023

Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA57070-1

Batch ID: 114327 Document Name: Size of file in bytes: 79872 File Name: 2023_07_18_7_3N_66W_Henrickson SGS
ECMC.xls

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 653338 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/18/2023

Collection Point: Stock Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA57055-1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
752520	403587258	2023_07_18_7_3N_66W_H enrickson_Wellhead.jpg	Photographs	JPG
752520	403587243	2023_07_18_7_3N_66W_H enrickson Isotech NG4.pdf	Analytical Laboratory Report	PDF
752520	403587255	2023_07_18_7_3N_66W_H enrickson_PrePost.jpg	Photographs	JPG
752520	403587251	2023_07_18_7_3N_66W_H enrickson SGS.pdf	Analytical Laboratory Report	PDF
752520	403587257	2023_07_18_7_3N_66W_H enrickson_Spigot.jpg	Photographs	JPG
752520	403587249	2023_07_18_7_3N_66W_H enrickson Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
752520	403587231	2023_07_18_7_3N_66W_H enrickson Isotech SIW.pdf	Analytical Laboratory Report	PDF
752520	403587254	2023_07_18_7_3N_66W_H enrickson_Loc.jpg	Photographs	JPG
752520	403587253	2023_07_18_7_3N_66W_H enrickson_FS_COGCC.pdf	Field Data Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	03/19/2024
Total: 1 comment(s)		