

## **Storm Water Management and Erosion control**

**Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad**

**Location #: 335804**



**Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 86 yards from East Fork Parachute Creek.**

**Section/Township/Range: 28 5S95W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad**  
**Location #: 335804**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad**  
**Location #: 335804**



**Photo # 182 Failure to maintain chemical BMP/Chemical containment approximately 1/2 to 5/8 full of fluid/BMP insufficient to contain possible spill.**