

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SENE

Location ID: 324184

Date: 3/15/2024



Wellheads – Photo #09958



Separators – Photo #09959



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SENE

Location ID: 324184

Date: 3/15/2024



**Tank Battery – Photo #09960**



**Lack of Stabilization – Photo #09961**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SENE

Location ID: 324184

Date: 3/15/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09962**



**Insufficient Administrative Control – Photo #09963**