

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 3/15/2024



Location Entrance – Photo #09975



Wellheads – Photo #09978

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 3/15/2024



Wellheads – Photo #09979



Separators – Photo #09977

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 3/15/2024



Tank Battery – Photo #09976



Unprotected Soil Stockpile – Photo #09982

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 3/15/2024



Unprotected Soil Stockpile – Photo #09983