

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SWNE

Location ID: 335653

Date: 3/15/2024



Wellheads – Photo #09996



Separators – Photo #00000

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SWNE

Location ID: 335653

Date: 3/15/2024



Tank Battery – Photo #09998



Lack of Stabilization – Photo #00001

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SWNE

Location ID: 335653

Date: 3/15/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00002**