

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 1: Location from entrance

Photo 2: Wellhead Sign (Faded)

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 3: Pumpjack

Photo 4: Weeds

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 5: Weeds

Photo 6: Weeds

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Energy & Carbon Management Commission
40.27405, -104.68365, 1476.9m, 323°
Mar 19, 2024 10:31:29



Energy & Carbon Management Commission
40.27392, -104.68375, 1478.9m, 15°
Mar 19, 2024 10:31:54

Photo 7: Weeds/ stained soil

Photo 8: (Faded) Tank Battery Sign

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Energy & Carbon Management Commission
40.27398, -104.68377, 1479.2m, 15°
Mar 19, 2024 10:32:07



Energy & Carbon Management Commission
40.27383, -104.68375, 1480.5m, 360°
Mar 19, 2024 10:32:34

Photo 9: No contents/capacity displayed

Photo 10: Weeds/debris

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 11: Weeds/debris

Photo 12: Weeds/debris

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 13: No signage displayed at tank, weeds

Photo 14: Weeds

Inspection Photos
Location Name: Musick-McClintock #1
Location ID: 332862



Photo 15: Weeds