

Inspection Photos
Location Name: Musick-McClintock #2
Location ID: 31633



Photo 1: Access road, overgrown vegetation



Photo 2: Overgrown vegetation

Inspection Photos
Location Name: Musick-McClintock #2
Location ID: 31633



Energy & Carbon Management Commission
40.27086, -104.68902, 1483.3m, 100°
Mar 19, 2024 12:55:39

Photo 3: Pumpjack, weeds/debris



Energy & Carbon Management Commission
40.27078, -104.68888, 1483.4m, 42°
Mar 19, 2024 12:56:02

Photo 4: Pumpjack Sign

Inspection Photos
Location Name: Musick-McClintock #2
Location ID: 318633



Photo 5: Weeds/debris



Photo 6: Weeds/debris