

Inspection Photos
Location Name: Sarafini 'B' 3
Location ID: 326735



Photo 1 Location.



Photo 2 Wellsite.

Inspection Photos
Location Name: Sarafini 'B' 3
Location ID: 326735



Photo 3 WH sign, monitoring equip.

Photo 4 WH.

Inspection Photos
Location Name: Sarafini 'B' 3
Location ID: 326735



Photo 5 Prime mover (gas engine).



Photo 6 WH/PJ.

Inspection Photos
Location Name: Sarafini 'B' 3
Location ID: 326735



Photo 7 Unused transformers.

API # 123-13529, UNUSED ELECTRICAL EQUIPMENT.



Photo 8 Archived photo of unused transformers from 10-14-2015.

Inspection Photos
Location Name: Sarafini 'B' 3
Location ID: 326735



Photo 9 Unused transformers facing the wellsite.