

Inspection Photos
Location Name: Jillson 3
Location ID: 336406



Energy & Carbon Management Commission
40° 77' - 104° 59' 47" 4902 30 00"
03/20/2024 14:15:28



Energy & Carbon Management Commission
40° 78' - 104° 59' 47" 4902 30 00"
03/20/2024 14:15:03

Photo 1 Location.

Photo 2 WH sign.

Inspection Photos
Location Name: Jillson 3
Location ID: 336406



Photo 3 WH.



Photo 4 Ancillary equip.

Inspection Photos
Location Name: Jillson 3
Location ID: 336406



Photo 5 Horse head lying on the ground.



Photo 6 electric panel/monitoring equipment.