

Caerus
B34NW
Location ID: 335102



Well heads



Separators

Caerus
B34NW
Location ID: 335102



ECD



Lack of tank battery signage

Caerus
B34NW
Location ID: 335102



Lack of tank battery signage




Lack of tank battery signage

Caerus
B34NW
Location ID: 335102



Labeling is illegible



Labeling is illegible

Caerus
B34NW
Location ID: 335102



Hole in secondary containment



Leaking valve and cap not installed properly

Caerus
B34NW
Location ID: 335102



Debris



Lack of stabilization/ compaction

Caerus
B34NW
Location ID: 335102



Lack of stabilization/ compaction



Lack of stabilization/ compaction