

# Final Reclamation Inspection

March 19th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326115

Inspection Document #: 714000573

La Plata County, CO

Township: SWSE 35 35N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Day V Ranch 35-2  
Location ID: 326115

3/19/24  
+37.252605,-107.822237  
318° NW



Photo 1. Overview of the disturbance taken from the entrance facing center.


Inspection Photos

Location Name: Day V Ranch 35-2

Location ID: 326115



3/19/24  
+37.252605,-107.822237  
318° NW



3/19/24  
+37.252949,-107.822515  
138° SE

**Photo 2.** View of the project area from the southeast and northwest corners facing center. Vegetation comprised of smooth brome.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07494

Inspection Photos  
Location Name: Day V Ranch 35-2  
Location ID: 326115

3/19/24  
+37.253149,-107.822768  
301° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Reference area comprised of smooth brome, sagebrush and rabbit brush.

API #: 067-07494