

**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**As signs are replaced additional information is required**



**Erosion and sediment migration**



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**Debris**



**Stained soil**



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**Debris**



**Soil staining**



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**As signs are replaced additional information is required**



**Missing label**



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**Unmarked anchor**



**Erosion and sediment migration**



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**Weeds. Erosion and sediment migration**



**Debris**



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**Pop off riser missing rain protection**



**Erosion and sediment migration**



KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277

Mar 19, 2024 at 12:36:58 PM

DATE	CALIBRATED		ORIFICE INSPECTED	PLATE SIZE	GAS SAMPLE TAKEN	COMMENTS
	Y/N	INITIALS				
5-28-15	Y	Ⓢ	NO	0.625	0.9624 yes	Sch. Cal. Ⓢ Kyrck
6-29-15	Y	Ⓢ	yes	0.625	0.9624 no	Sch. Cal. Ⓢ Kyrck
8-27-15	Y	Ⓢ	no	0.625	0.9533 no	Sch. Cal. J. Schmsenke
11-23-15	Y	Ⓢ	yes	0.625	0.9533 yes	Sch. Cal. J. Schmsenke
2-27-16	Y	Ⓢ	no	0.625	no	Sch. Cal. J. Schmsenke
8-17-16	Y	Ⓢ	yes	0.625	no	Sch. Cal. J. Schmsenke
2-27-17	Y	Ⓢ	no	0.625	no	Sch. Cal. J. Schmsenke
8-30-17	Y	Ⓢ	yes	0.625	no	Sch. Cal. J. Schmsenke
8-21-18	Yes	KB	Yes	.625	Yes	Spectra KB
2-26-19	Y	KB	Yes	.625	Yes	KB
10-1-19	Yes	KB	Yes	.625	Yes	KB .9055
1-25-22	Y	KB	Y	.625	No	KB

Calibration out of date



Open to wildlife



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



Mar 19, 2024 at 12:25:59 PM

**Location from Northeast corner**



Mar 19, 2024 at 12:31:32 PM

**Location from Northwest corner**



**KT Resources LLC  
WRD Federal 19-11  
Location ID: 316277**



**Location from Southwest corner**



**Location from Southeast corner**