

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



As signs are replaced additional information is required



Hole under containment

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



Leaking containment



Leaking containment

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



As signs are replaced additional information is required




Leak. Soil staining.

KT Resources LLC
WRD Unit 28-22
Location ID: 316281



Debris



Calibration not current

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



Location from Southwest corner



Location from Southwest corner

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



Location from Northeast corner



Location from Southeast corner