

Inspection Photos
Location Name: Grant 3
Location ID: 318532



Photo 1 Location.



Photo 2 Dead vegetation and trash around the WH.

Inspection Photos
Location Name: Grant 3
Location ID: 318532



Photo 3 Dead vegetation and trash around the WH.



Photo 4 Dead vegetation and trash around the wellsite.

Inspection Photos
Location Name: Grant 3
Location ID: 318532



Photo 5 Dead vegetation and trash around the WH.



Photo 6 WH sign.

Inspection Photos
Location Name: Grant 3
Location ID: 318532



Photo 7 Electric panel, electric motor & pump jack.



Photo 8 Trash by the ancillary equipment.

Inspection Photos
Location Name: Grant 3
Location ID: 318532



Photo 9 Trash around location.



Photo 10 Trash around location.