

**Inspection Photos**  
**Location Name: Grant 4**  
**Location ID: 311319**



**Photo 1 Location.**



**Photo 2 Dead vegetation(debris) just outside of wellsite fencing.**



Inspection Photos  
Location Name: Grant 4  
Location ID: 311319



Photo 3 WH.



Photo 4 WH sign.





**Inspection Photos**  
**Location Name: Grant 4**  
**Location ID: 311319**



**Photo 5 Dead vegetation(debris) between the wellsite fencing & pump jack fencing.**



**Photo 6 Electric panel, pump jack.**

**Inspection Photos**  
**Location Name: Grant 4**  
**Location ID: 311319**



**Photo 7 Ancillary equip.**