

Inspection Photos
Location Name: Thomas L Russell 'B'2
Location ID: 318280



Photo 1 Location.

Photo 2 WH sign.

Inspection Photos
Location Name: Thomas L Russell 'B'2
Location ID: 318280



Photo 3 Dead vegetation(debris) inside & outside of the wellsite fencing.



Photo 4 Dead vegetation(debris) around the ancillary equip.

Inspection Photos
Location Name: Thomas L Russell 'B'2
Location ID: 318280



Photo 5 Dead vegetation(debris) inside & outside of the wellsite fencing Pump Jack.



Photo 6 Dead vegetation(debris) inside the wellsite fencing around PJ base.

Inspection Photos
Location Name: Thomas L Russell 'B'2
Location ID: 318280



Photo 7 Dead vegetation(debris) inside of the wellsite fencing.



Photo 8 Dead vegetation(debris) inside the wellsite fencing around PJ base.

Inspection Photos
Location Name: Thomas L Russell 'B'2
Location ID: 318280



Photo 9 Dead vegetation(debris) by the WH.



Photo 10 WH.