

Final Reclamation Inspection

March 19th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325537

Inspection Document #: 714000578

La Plata County, CO

Township: SENW 31 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State Chastain 01-31 1
Location ID: 325537



Photo 1. Overview of the disturbance taken from the entrance facing center.



API #: 067-06571



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: State Chastain 01-31 1

Location ID: 325537



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Unused and surface owner equipment corrective action identified in the previous inspection doc #714000050 has been addressed/resolved.

API #: 067-06571

Inspection Photos

Location Name: State Chastain 01-31 1

Location ID: 325537



3/19/24

+37.261946,-107.790200

325° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Weedy debris corrective action identified in the previous inspection doc #714000050 has been addressed/resolved.

API #: 067-06571

Inspection Photos
Location Name: State Chastain 01-31 1
Location ID: 325537



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the southern interim reclamation area facing southeast.
Vegetation comprised of smooth brome.

API #: 067-06571

Inspection Photos

Location Name: State Chastain 01-31 1

Location ID: 325537



3/19/24

+37.261988,-107.790312

285° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of Reference area comprised of smooth brome and gambel oak.

API #: 067-06571