



## WELL SITE INSPECTION FORM

SCANNED



WELL NAME LMAR LIVESTOCK #1-29X API NUMBER 05 - 099 - 06293  
OPERATOR MURFIN DRILLING PERMIT NUMBER 88 1092  
LOCATION SE NW 29 21S 46W COUNTY PROVERS  
FIELD WILDCOT INSPECTOR SHELTON

## AL/PA/DA INSPECTION RESULTS:

PASS(Y)      FAIL(N) N DATE 2/9/89 WELL STATUS: FN      FD      WO     

=====

DATE OF INSPECTION BEFORE/DURING DRILLING                     

CASING SIZE      DEPTH SET      CMT VOL      WOC       
CONSISTENT WITH APD CASING PROGRAM?      RETURNS       
RIG      BOP'S      CONTACT     

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION                     

PIPE SET?      COMPLETION RIG/ACTIVITY                       
DRILLING PITS: CLOSED      OPEN      WELLHEAD SYSTEM INSTALLED       
TANK ID: YES      NO      NA      WELL SIGN: YES      NO       
SKIM PIT:      gal TANKS: (      )      bbls  
EQUIPMENT                     

BRADENHEAD PRESSURE      FLUID: NO      YES      TYPE       
METER RUN: YES      NO      WELL STATUS: PR      TA      SI      WELL CAT 3-     

## AL/PA/DA INSPECTION

DATE PLUGGED: 11/12/88 DATE PERMIT EXPIRED:                       
HOLE PLUGGED: YES X NO      PITS BACKFILLED: YES      NO X  
MATERIAL BURIED: YES      NO      NA X SITE CLEAN: YES X NO       
BOND RELEASE OK: YES      NO X FED      HOLE MARKER: YES      NO X

DATE OF SAFETY/STATUS INSPECTION 2/9/89

COMMENTS NO SIGN OF CSG / SITE PARTIALLY RESTORED BUT  
STILL ROUGH / SOME CIRCULATION ATTS OPEN, FROZEN