

VERBAL REQUESTS

NOTICE OF INTENTION TO DRILL _____


Bonding Status _____

SCANNED

NOTICE OF INTENTION TO ABANDON _____

OTHER Verbal approval form #10
Mo-Pet.-Co. - gatherer

DISC.



COMPANY Frankfort ADDRESS _____

WELL NO. 9-1 BY Saunders PHONE NO. _____

LEASE State TITLE _____ EXT. _____

COUNTY Bent FIELD Unnamed

Location CSE NW Section 9 Township 21S Range 48W Meridian 6+1
(quarter quarter)
_____ feet from _____ Section line and _____ feet from _____ Section line
N or S E or W

DETAILS OF PLAN OF WORK: T.D. _____ FORMATION _____

ESTIMATED DATE OF WORK: _____ ESTIMATED TIME: _____

APPROVED BY: DVR

DATE 12-23-59

✓
27

MEMO

TO: D. V. Rogers

FROM: F. J. Piro

SUBJECT: Field Trip - McClave Field and Southeastern Colorado - July 23-26, 1963

An inspection trip was made to the McClave Field during the period of July 23 - 26, where testing of the gas wells was in progress.

The tests were being conducted by Thurmond-McGlothlin of Pampa, Texas, (Jack Chisum, field engineer). Each well has been equipped with a permanent set-up of a Rotary Positive Displacement type gas meter (Emcorector Type I). Due to avoidance of interruption of gas deliverability from the field, a few wells were put on test at one time. The wells were allowed to stabilize their flow from 20 - 24 hours prior to the test. There are separate gas meters on those wells that are dually completed. A close check was being maintained on tubing and casing pressures during the test. The testing commenced July 22 and is expected to take approximately 20 days to complete. A report is to be submitted to this office regarding the results, as well as G. P. M. analysis of the gas.

A gas plant is located in the southern portion of the field (Sec. 26, 20S-48W). The plant was built by the Bering Corp. of Dallas, Texas, but is being operated by Fleetwood Drilling Co. It is a small plant, and there is no permanent personnel. Periodic checks are made by a contract worker (Howard Johnson, Wiley, Colo., a nearby town on Highway 287). I was unable to contact anyone to find out more definite information, such as capacity, etc.

A visit was made to the No. 2 Hoff Heirs well, located in the SW NE, 35-29S-60W, Model Dome Field, Las Animas County. Only this one well was drilled by the operator, Robert E. Thorpe. A rancher, A. C. Morris, who lives in the area, was familiar with the operations. However, he does not know the present whereabouts of Thorpe, and had always thought he had a Denver office. The well is shut in, and a check of the files shows that all forms required are in. I was also informed by Morris that at least 2 or 3 wells were drilled during the past year in an area north of Thatcher, Colorado. No one seems to know who the operators were. The wells were quickly drilled and plugged.

FJP:cm

76