

Inspection Photos

Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI 36-24 Pad

Location ID: 324250



Photo # 224 From entrance to location



Photo # 225 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI 36-24 Pad

Location ID: 324250



Photo # 226 Location



Photo # 227 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI 36-24 Pad

Location ID: 324250



Jan 23, 2024 at 12:58:22 PM
CO



Mar 18, 2024 at 12:42:50 PM
CO

**Photo # 3601 from inspection 708902866 conducted on
01/23/2024 Unused equipment**

Photo # 228 Unused equipment

Inspection Photos

Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI 36-24 Pad

Location ID: 324250



Jan 23, 2024 at 1:02:25 PM
CO

Photo # 3602 from inspection 708902866 conducted on
01/23/2024 Unused equipment



Mar 18, 2024 at 12:43:36 PM
CO

Photo # 229 Unused equipment

Inspection Photos

Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI 36-24 Pad

Location ID: 324250



Photo # 230 Open ended piping on unused equipment is a wildlife hazard



Photo # 232 Open ended piping on unused equipment is a wildlife hazard