

Inspection Photos

API: 043-06194

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 3/20/2024

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the wellsite location.



Inspection Photos



Photo 2. Facing southeast toward the wellsite.



Inspection Photos



Photo 3. Facing back northwest. There is an offsite tank battery shown at red arrow.



Inspection Photos



Photo 4. Facing southwest toward the offsite tank battery which has 6 tanks. Signs has been posted at the tank battery.



Inspection Photos



Photo 5. Facing southeast toward the offsite tank battery. The risers have been removed from this area. Unused areas of the location must be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:417859 | Date: 3/20/2024