

# Inspection Photos

Loc: 322263

Operator: **JAVERNICK OIL**

Inspection Date: 3/20/2024

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 3.** Facing southwest at the abandoned wellsite. There is a pipe at red arrow and wood block.





## Inspection Photos



**Photo 2.** There is stained soils at red arrow and a metal rod.

