

Stormwater Inspection

Date: 3/18/24

Operator: Noble Energy Inc - 10322

Location ID: 429922

Inspection Document #: 713900464

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Moser PC G34-65HN Tank

Location ID: 429922



Photo 1. The photo was taken at the tank battery location facing Northwest. The photo illustrates erosion on the South side of the production pad.



Photo 2. The photo was taken at the tank battery location facing South. The photo illustrates erosion on the North side of the production pad.

Inspection Photos
Location Name: Moser PC G34-65HN Tank
Location ID: 429922



Photo 3. The photo was taken at the tank battery location facing West. Refer to the comment for photo 2.