

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Latham U-14 PAD

Loc ID: 437416

Inspection: 713900419



Exhibit A

CA: Broken cable is daylighting in the Northwest corner of the disturbance area just off the production pad in the interim area. Remove all debris and waste to comply with 1003 interim reclamation rules.

CA Resolution: Operator has reported that the broken cable has been appropriately removed to comply with Rules 1003 and 606.