

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 7 Pad

Location ID: 335570



Photo # 664 From entrance to location



Photo # 665 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 7 Pad
Location ID: 335570



Photo # 666 Location



Photo # 667 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 7 Pad
Location ID: 335570




Photo # 668 Location



Photo # 669 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 7 Pad

Location ID: 335570



Photo # 670 Location



Photo # 671 Debris