

Interim Reclamation and Stormwater Inspection

March 19, 2024

Operator: Crestone Peak Resources #10633

Location ID: 437930

Inspection Document #: 709400982

Weld County, CO

NENW Section 32 T2N R64W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Newnam 32H-C264
Location ID: 437930



Photo 1. Photo taken facing north of location sign.



Photo 2. Photo taken facing north of of wellheads.



Inspection Photos
Location Name: Newnam 32H-C264
Location ID: 437930



Photo 3. Photo taken facing south of weeds (kochia & russian thistle) on well pad entrance.



Photo 4. Photo taken facing east of weeds (kochia & russian thistle) on well pad south side.

Inspection Photos
Location Name: Newnam 32H-C264
Location ID: 437930



Photo 5. Photo taken facing east of weeds (kochia & russian thistle) on well pad on the east side of pad.



Photo 6. Photo taken facing south of weeds (kochia & russian thistle) and trash (wood boards) on well pad on the west side of pad.

Inspection Photos

Location Name: Newnam 32H-C264

Location ID: 437930



Photo 7. Photo taken facing northwest of tank battery on site.



Photo 8. Photo taken facing northwest of weeds (kochia & russian thistle) at entrance of tank battery.



Inspection Photos

Location Name: Newnam 32H-C264

Location ID: 437930



Photo 9. Photo taken facing west of weeds (kochia & russian thistle) on south side of tank battery.

Photo 10. Photo taken facing south of weeds (kochia & russian thistle) on east side of tank battery.



Inspection Photos
Location Name: Newnam 32H-C264
Location ID: 437930



Photo 9. Photo taken facing north of weeds (kochia & russian thistle) on east side of tank battery.



Photo 10. Photo taken facing south of weeds (kochia & russian thistle) on west side of tank battery.

