

# Final Reclamation Inspection

March 19th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326462

Inspection Document #: 714000583

La Plata County, CO

Township: NENW 6 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Kendrick 3-6  
Location ID: 326462



3/19/24

+37.249099,-107.788486

58° NE

Photo 1. Overview of the disturbance taken from the entrance facing center.



3/19/24

+37.249249,-107.787897

55° NE

Hilcorp Energy Company  
KENDRICK 3-6  
LAT: 37.24912 LONG: -107.787873  
UNIT C, SEC. 06, T034N, R008W  
S07 FWL & S200 FWL  
API NO. 05-067-08147  
LEASE & FEE ELEV. 7048  
LA PLATA COUNTY, CO  
7 MILES S. OF ROAD 236  
EMERGENCY NUMBERS: 800-326-8170 OR 911  
NO SMOKING NO TRESPASSING

API #: 067-98147



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Kendrick 3-6  
Location ID: 326462

3/19/24  
+37.248978,-107.788282  
79° E



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the southern interim reclamation area facing south.  
Vegetation comprised of smooth brome and intermediate wheatgrass.

API #: 067-98147

Inspection Photos  
Location Name: Kendrick 3-6  
Location ID: 326462



3/19/24  
+37.249248,-107.788635  
215° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Debris corrective action identified in the previous inspection doc #714000048 has been addressed/resolved.

API #: 067-98147

Inspection Photos  
Location Name: Kendrick 3-6  
Location ID: 326462

3/19/24  
+37.249310,-107.787927  
2° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of the reference area comprised of smooth brome.

API #: 067-98147