

Final Reclamation Inspection

March 19th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326291

Inspection Document #: 714000584

La Plata County, CO

Township: NESE 6 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SE Durango Wride 6-1
Location ID: 326291



3/19/24
+37.259001,-107.788719
134° SE

Photo 1. Overview of the disturbance taken from the entrance facing center.



3/19/24
+37.242247,-107.781228
38° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07787

Inspection Photos

Location Name: SE Durango Wride 6-1

Location ID: 326291



3/19/24
+37.242118,-107.781240
159° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area comprised of smooth brome.

API #: 067-07787

Inspection Photos

Location Name: SE Durango Wride 6-1

Location ID: 326291



Photo 3. Unused panel observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07787

Inspection Photos
Location Name: SE Durango Wride 6-1
Location ID: 326291



3/19/24
+37.242247,-107.781228
331° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the reference area comprised of smooth brome.

API #: 067-07787