

Final Reclamation Inspection

March 19th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326255

Inspection Document #: 714000585

La Plata County, CO

Township: SWNW 8 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**


Department of Natural Resources

Inspection Photos
Location Name: Hill 8-2
Location ID: 326255



3/19/24
+37.232489,-107.776621
123° SE

Photo 1. Overview of the disturbance taken from the entrance facing center.



3/19/24
+37.232578,-107.776735
52° NE

Inspection Photos
Location Name: Hill 8-2
Location ID: 326255



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Weeds corrective action identified in the previous inspection doc #714000063 has been addressed/resolved.

API #: 067-07732

Inspection Photos
Location Name: Hill 8-2
Location ID: 326255



Photo 3. View of weedy kochia debris piling up along the western and northern fence line.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07732

Inspection Photos
Location Name: Hill 8-2
Location ID: 326255



Photo 4. View of unused piping and panels observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07732

Inspection Photos
Location Name: Hill 8-2
Location ID: 326255



3/19/24
+37.232440,-107.776289
-256° W

Photo 5. View of unmarked guy line anchor on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07732

Inspection Photos
Location Name: Hill 8-2
Location ID: 326255



3/19/24
+37.232108,-107.776056
187° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of reference area comprised of smooth brome, western wheatgrass and tumble mustard.

API #: 067-07732