

Final Reclamation Inspection

March 19th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 325538

Inspection Document #: 714000586

La Plata County, CO

Township: SWNE 7 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



3/19/24
+37.236087,-107.783487
317° NW




Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



Photo 2. Weeds and debris corrective action identified in the previous inspection doc #714000062 has been addressed/resolved.

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the southern interim reclamation area facing east.
Vegetation comprised of smooth brome.

API #: 067-06574

Inspection Photos
Location Name: Freienmuth 1-7
Location ID: 325538



Photo 4. View of the reference area comprised of smooth brome.