

Final Reclamation Inspection

March 19th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326249

Inspection Document #: 714000587

La Plata County, CO

Township: NENW 17 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



3/19/24
+37.219453,-107.773232
111° E




Photo 1. Overview of the disturbance taken from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07720

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Debris corrective action identified in the previous inspection doc #714000070 has been addressed/resolved.

API #: 067-07720

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



3/19/24
+37.219642,-107.772903
306° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of northern interim reclamation area facing north west. Minimal vegetation observed as disturbance is surrounded by an active prairie dog colony.

API #: 067-07720

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249



Photo 4. 2 unmarked guy line anchors observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07720

Inspection Photos
Location Name: James Cole A 1
Location ID: 326249

