

Final Reclamation and Stormwater Inspection

March 22, 2024

Operator: Crestone Peak Resources #10633

Location ID: 450929

Inspection Document #: 709400982

Weld County, CO

NEWW Section 29 T1N R68W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Photo 1. Photo taken facing east of location



Photo 2. Photo taken facing north of location and equipment parked on site.

Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Photo 3. Photo taken facing south of weeds (kochia & russian thistle) on east side of site.



Photo 4. Photo taken facing south of weeds (kochia & russian thistle) on west side of pad.



Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Photo 5. Photo taken facing east of weeds (kochia & russian thistle) on south cutslope side of pad.



Photo 6. Photo taken facing east of weeds (kochia & russian thistle) and stormwater erosion on south cutslope side of pad.

Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Photo 7. Photo taken facing east of stormwater erosion on southeast cut slope side of pad.



Photo 8. Photo taken facing north of weeds (kochia & russian thistle) on topsoil stockpile.

Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Mar 22, 2024 at 10:47:06 AM
Erie CO 80516
United States



Mar 22, 2024 at 10:48:57 AM
Erie CO 80516
United States

Photo 9. Photo taken facing north of weeds (kochia & russian thistle) on east side of pad.

Photo 10. Photo taken facing west of weeds (kochia & russian thistle) on north side of pad.

Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Photo 11. Photo taken facing north of large slough of pad surface from stormwater erosion.



Photo 12. Photo taken facing north of large slough of pad surface from stormwater erosion.

Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Photo 13. Photo taken facing north of large slough of pad surface from stormwater erosion leading off site. .



Photo 14. Photo taken facing south of large slough area of pad surface from stormwater erosion.

Inspection Photos
Location Name: Pratt 29H-P168-TCA
Location ID: 450929



Photo 15. Photo taken facing west of dumped soil and water from a vac truck on the northwest side of pad.



Photo 16. Photo taken facing east of dumped soil and water from a possibly a vac truck leading off site into vegetated area on the northwest side of pad.