

Inspection Photos

3/18/2024

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335993

Inspection Doc: 696205695

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335993



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast and south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335993



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335993



Photo 3: Photos examples showing 1) anchors missing required marking and 2) stained soils observed around the wells.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335993



March 18, 2024

Photo 4: Anchors missing required marking.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335993



Photo 5: Photos examples showing tanks missing required cap/plug.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335993



Photo 6: Photos examples showing the interim areas of the Location. Heavy grazing pressure evident- long term continuous grazing may hinder reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources