

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 1 – Pumping Unit



Photo 2 – Stained Soil at Wellhead

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 3 – Wellhead



Photo 4 – Wellhead – Stained Soil

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875




Photo 5 – Wellhead



Photo 6 – Gas Engine

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 7 – Stained Soil



Photo 8 – Stained Soil

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 9 – Stained Soil



Photo 10 – Tank Battery

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 11 – Stained Soil



Photo 12 – Stained Soil at Loadline

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 13 – Heater Treater and ECD




Photo 14 – Sales Line LOTO