

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 3/25/2024



Location Entrance – Photo #00029

Wellheads – Photo #00030

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 3/25/2024



Separators – Photo #00031



Tank Battery – Photo #00034

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 3/25/2024



Lack of Stabilization – Photo #00032



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00035**