

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/28SWSW

Location ID: 324069

Date: 3/25/2024



Wellhead – Photo #00066



Separators – Photo #00064

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/28SWSW

Location ID: 324069

Date: 3/25/2024



Tank Battery – Photo #00062



Lack of Stabilization/Degradation – Photo #00067

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/28SWSW

Location ID: 324069

Date: 3/25/2024



Lack of Stabilization/Degradation – Photo #00068