

Inspection Photos
Location Name: Betz State PC G 10-33D
Location ID: 420254



Photo 1: Wellhead sign, slightly damaged

Photo 2: Wellhead

Inspection Photos
Location Name: Betz State PC G 10-33D
Location ID: 420254




Photo 3: Tank Battery Sign

Photo 4: Tank Battery, damaged signage

Inspection Photos
Location Name: Betz State PC G 10-33D
Location ID: 420254




Photo 5: Damaged signage

Photo 6: Damaged signage

Inspection Photos
Location Name: Betz State PC G 10-33D
Location ID: 420254



Photo 7: Damaged signage