

Inspection Photos
Location Name: Energy Minerals Unit B 1
Location ID: 318873



Photo 1 Location.



Photo 2 WH.

Inspection Photos
Location Name: Energy Minerals Unit B 1
Location ID: 318873



Photo 3 WH sign is missing operator information.



Photo 4 Pump Jack.

Inspection Photos
Location Name: Energy Minerals Unit B 1
Location ID: 318873



Photo 5 Debris (Dead vegetation) around location ROW & ancillary equipment.



Photo 6 Debris (Dead vegetation) around location ROW & ancillary equipment.

Inspection Photos
Location Name: Energy Minerals Unit B 1
Location ID: 318873



Photo 7 Debris (Dead vegetation) around location ROW & ancillary equipment.



Photo 8 Debris (Dead vegetation) around location ROW & ancillary equipment.

Inspection Photos
Location Name: Energy Minerals Unit B 1
Location ID: 318873



Photo 9 Debris (Dead vegetation) around location ROW & ancillary equipment.