

Final Reclamation Inspection

March 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 385900

Inspection Document #: 714000597

La Plata County, CO

Township: NWNE 3 34N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fischer Mark Federal B 3
Location ID: 385900

3/22/24
+37.247250,-107.514036
17° N



Photo 1. Overview of the disturbance taken from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08525

Inspection Photos

Location Name: Fischer Mark Federal B 3

Location ID: 385900



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Sign/Placard Corrective action identified in the previous inspection doc #712700435 has been addressed/resolved.

API #: 067-08525

Inspection Photos
Location Name: Fischer Mark Federal B 3
Location ID: 385900

3/22/24
+37.247316,-107.513804
59° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the eastern interim reclamation area facing northeast.

API #: 067-08525

Inspection Photos

Location Name: Fischer Mark Federal B 3

Location ID: 385900



3/22/24
+37.247834, -107.513840
333° NW



3/22/24
+37.247546, -107.514151
335° NW

Photo 4. View of rill erosion forming in two different spots in the western interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08525

Inspection Photos

Location Name: Fischer Mark Federal B 3

Location ID: 385900



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of unused oil and gas fitting equipment observed on location.

API #: 067-08525

Inspection Photos
Location Name: Fischer Mark Federal B 3
Location ID: 385900

3/22/24
+37.247216,-107.514197
186° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of reference area comprised of smooth brome, sage brush and juniper.

API #: 067-08525