

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Debris



Debris

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



When replaced additional information is required



Unused equipment

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Relief riser missing rain protection



Production separators and manifolds from Southeast corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



**Production tank and chemical station from Northeast corner
of well pad**



Location from Northwest corner of well pad

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Location from Southwest corner of well pad



Location from Southeast corner of well pad