


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Mar 25, 2024 at 9:20:46 AM  
CO



Mar 25, 2024 at 9:23:32 AM  
CO

Photo # 1077 From entrance to location

Photo # 1078 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1079 Location



Photo # 1080 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1081 Location



Photo # 1082 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486




Photo # 1083 Location



Photo # 1084 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1085 Location



Photo # 1086 PRV does not comply with CECMC pressure safety device rules



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Mar 25, 2024 at 9:34:34 AM  
CO

**Photo # 1087 Stored equipment/supplies in the interim area**



Mar 25, 2024 at 9:34:07 AM  
CO

**Photo # 1088 Stored vehicles in the interim area & partially in ditch/BMP**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



**Photo # 1089 Stored vehicles in the interim area & partially in ditch/BMP**



**Photo # 1090 Stored equipment/supplies on location**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Mar 25, 2024 at 9:29:25 AM  
CO

Photo # 1091 Stored equipment/supplies on location



Mar 25, 2024 at 9:29:45 AM  
CO

Photo # 1092 Stored equipment/supplies on location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1093 Debris

