

Inspection Photos  
Location Name: Albert Sack D #3  
Location ID: 320021



Photo 1 loc pic



Photo 2 Well head



Inspection Photos  
Location Name: Albert Sack D #3  
Location ID: 320021



Photo 3 Debris around electric equipment



Photo 4 Debris around electric equipment