

Inspection Photos
Location Name: Lamb-Dalton Nesssu 13
Location ID: 317947



Photo 1 Location.



Photo 2 Wellsite.

Inspection Photos
Location Name: Lamb-Dalton Nesssu 13
Location ID: 317947



Photo 3 WH.



Photo 4 WH sign.

Inspection Photos
Location Name: Lamb-Dalton Nessu 13
Location ID: 317947



Photo 5 Ancillary equip.



Photo 6 Stained soil.

Inspection Photos
Location Name: Lamb-Dalton Nesssu 13
Location ID: 317947



Photo 7 Stained soil at the PJ base.




Photo 8 Stained soil.

Inspection Photos
Location Name: Lamb-Dalton Nesssu 13
Location ID: 317947



Photo 9 Debris (dead vegetation and trash) at the PJ base.



Photo 10 Debris (dead vegetation and trash) in the PJ base.

Inspection Photos
Location Name: Lamb-Dalton Nesssu 13
Location ID: 317947



Photo 11 Debris (dead vegetation and trash) at the PJ base.