

Interim Reclamation Inspection

Date: 3/22/24

Operator: Noble Energy Inc - 100322

Location ID: 317727

Inspection Document #: 713900482

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Moser-Dechant 18-H26 Tank

Battery

Location ID: 317727



Photo 1. The photo was taken at the entrance to the well location facing South. The photo illustrates the tumbleweeds stuck around the location.

Photo 2. The photo was taken at the tank battery location facing North. The photo illustrates the bunches of tumbleweeds stuck in the fencing along the tank battery.

Inspection Photos

Location Name: Moser-Dechant 18-H26 Tank

Battery

Location ID: 317727



Photo 3. The photo was taken at the tank battery location facing North. Refer to the comment for photo 2.

Photo 4. The photo was taken at the tank battery location facing South. Refer to the comment for photo 2.