

**Inspection Photos**  
**Location Name: Park T-4 Pad**  
**Facility ID: 482414**



**Missing OOSLAT Tag**




**Missing OOSLAT Tag**



**Inspection Photos**  
**Location Name: Park T-4 Pad**  
**Facility ID: 482414**



**Missing OOSLAT Tag**



**Missing OOSLAT Tags**



**Inspection Photos**  
**Location Name: Park T-4 Pad**  
**Facility ID: 482414**



**Missing OOSLAT Tag**



**Missing OOSLAT Tags**



**Inspection Photos**  
**Location Name: Park T-4 Pad**  
**Facility ID: 482414**



**Missing OOSLAT Tag**



**Missing OOSLAT Tag**



**Inspection Photos**  
**Location Name: Park T-4 Pad**  
**Facility ID: 482414**



**Missing OOSLAT Tags**



**Missing OOSLAT Tags**



**Inspection Photos**  
**Location Name: Park T-4 Pad**  
**Facility ID: 482414**



**Missing OOSLAT Tags**



**Missing OOSLAT Tags**



**Inspection Photos**  
**Location Name: Park T-4 Pad**  
**Facility ID: 482414**



**Missing OOSLAT Tags**



**Unused Hose**