

Inspection Photos
Location Name: UPRR 36 PAN AM C #2
Location ID: 332904



Photo 1: Wellhead sign




Photo 2: Wellhead

Inspection Photos
Location Name: UPRR 36 PAN AM C #2
Location ID: 332904



Photo 3: Location from entrance



Photo 4: Tank Battery Signs

Inspection Photos
Location Name: UPRR 36 PAN AM C #2
Location ID: 332904



Photo 5: Centralized tank battery



Photo 6: Debris

Inspection Photos
Location Name: UPRR 36 PAN AM C #2
Location ID: 332904



Photo 7: Debris



Photo 8: Debris

Inspection Photos
Location Name: UPRR 36 PAN AM C #2
Location ID: 332904



Photo 9: Debris



Photo 10: Debris

Inspection Photos
Location Name: UPRR 36 PAN AM C #2
Location ID: 332904




Photo 11: Debris



Photo 12: Debris

Inspection Photos
Location Name: UPRR 36 PAN AM C #2
Location ID: 332904



Energy & Carbon Management Commission
40.26494, -104.66617, 1450.7m, 117°
Mar 27, 2024 11:32:13

Photo 13: Debris