

McManus 33-22 2

Date completed 3/25/2024

Document #714000409

Cleanup wellhead.

Repaired secondary muffler and removed stained soil.



Remove trash.

