


Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838




When replaced additional information is required

Stained soil

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Debris



Damaged tank label

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Debris



No sign at tank battery

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Debris



Unmarked anchor

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Unmarked anchor



Unmarked anchor

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Unmarked anchor



Unmarked anchor

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Separator relief riser missing rain protection



Manifold relief risers missing rain protection

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Mar 28, 2024 at 12:31:25 PM



Mar 28, 2024 at 12:31:40 PM

Debris. Bear proof if used as a trash container or place inside

Debris

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



When replaced additional information is required



Production facility from Southwest corner of well pad

**Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838**



Well pad from Northwest corner



Well pad from Northeast corner

Caerus Piceance LLC
Piceance Creek Unit T33X-29G
Location ID: 311838



Well pad from Southeast corner



Well pad from Southwest corner