

Inspection Photos

API: 017-06507

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 3/26/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. There is a pile of oily E&P waste at the south side of the well. It appears there was a leak at the well and impacted material has not been cleaned and there are even vehicle track thru the oily waste pile.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06507 | Date: 3/26/2024

Inspection Photos



Photo 3. Facing toward the well. There are stained soils around the well which appear to have sprayed out oil to the south of the well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06507 | Date: 3/26/2024

Inspection Photos



Photo 4. Facing southeast. There are stained soils and the shed is stained black from the leak that occurred from the well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06507 | Date: 3/26/2024

Inspection Photos



Photo 5. Facing southeast. There are stained soils and the shed is stained black from the leak that occurred from the well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06507 | Date: 3/26/2024