

Inspection Photos

Loc: 321579

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/26/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward wellsite location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321579 | Date: 3/26/2024

Inspection Photos



Photo 2. There is oil stained soils around the wellhead that must be cleaned up. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321579 | Date: 3/26/2024

Inspection Photos



Photo 3. There is oily soils at the base of the shed.



Inspection Photos



Photo 4. View of inside the shed shows a leak occurring from the pumpjack engine. This needs to be controlled and cleaned up.

